New Hampshire Department of Transportation

Bridge Inspection Report

NBI Structure Number: 007401660008200

Effingham 166/082

Existing Bridge Section

Bureau of Bridge Design

GRANITE ROAD

SOUTH RIVER

Date of Inspection: 08/16/2019 Date Report Sent: 01/17/2020

Owner: Municipality

Bridge Inspection Group: C-Team Bridge Maintenance Crew: OTHER

> Critical deficiency sent 8/25/2015 due to severe section losses and large web holes at the beam ends at abutments. BRIDGE CLOSED.

Recommended Postings:

Weight: 'Bridge Closed' and barricaded at both ends

CLOSED AND BARRICADED 8/16/2019.

Weight Sign OK

Width: Narrow Bridge

Bullet holes in signs, still legible.

✓ Width Sign OK

Primary Height Sign Recommendation: None

99.99 Clearances: Over:

✓ Height Sign OK

Optional Centerline Height Sign Rec: None

Under: (Feet) 0.00

Route: 99.99

Condition:

Red List Status: Municipal Redlist

Culvert: N N/A (NBI)

14.0ft

17.8ft

14.0 ft

0.0 ft

Deck: 5 Fair

Superstructure: 2 Critical

Substructure: 5 Fair

Sufficiency Rating: - 36 %

Structure Type and Materials:

Number of Main Spans:

Number of Approach Spans:

Main Span Material and Design Type

Steel Continuous/Stringer/Girder

Bridge Rail: Substandard

Rail Transition: Substandard

Bridge Approach Rail: Substandard

Approach Rail Ends: Substandard

NH Bridge Type: IB-C (I Beams w/ Concrete Deck)

Deck Type: Concrete-Cast-in-Place

Wearing Surface: Other

Membrane: None

Deck Protection: None

Curb Reveal: Not Measured

Plan Location: N-O-F

Total Bridge Length:

36.0 ft

Right Curb/Sidewalk Width:

0.0ft

Total Bridge Width:

18.5ft

Median: No median

Bridge Skew: 0.00°

Year Built/Rebuilt: 1920/1950

NHDOT 008 Inspection

Bridge Dimensions:

Length Maximum Span:

Width Curb to Curb:

(W/Shoulders)

Left Curb/Sidewalk Width:

Approach Roadway Width:

Effingham 166/082

Printed on: 1/17/2020 10:06:48 AM Page 1 of 4

FER - 4 BECID

New Hampshire Department of Transportation

Bridge Inspection Report

NBI Structure Number: 007401660008200

Existing Bridge Section Bureau of Bridge Design

Effingham 166/082

Bridge Service:

Type of Service on Bridge: Highway Type of Service Under: Waterway

> Lanes on Bridge: 2 Lanes Under: 0

> > Future AADT:

AADT:

92

136

Percent Trucks:

Year of AADT: 2017

Year of Future AADT: 2040

Federal or State Definition Bridge: Fed-Definition Bridge

National Highway System: Bridge does not carry NHS

Roadway Functional Class: Rural, Local

New Hampshire Bridge Tier: 5

Eligibility for the National Register of Historic Places: Possibly eligible for

Traffic Direction: 2-way traffic

National Bridge Inventory (NBI) Appraisal Ratings:

Deck Geometry: 3 Intolerable - Correct Underclearances: N Not applicable (NBI) Approach Alignment: 6 Equal Min Criteria

Structural Evaluation: 0 Closed

Channel/Channel Protection: 6 Bank Slumping

Waterway Adequacy: 8 Equal Desirable Bridge Scour Critical Status: 3 SC - Unstable Riprap Condition: Fair Condition

Debris Present: Debris Present

Channel Notes: DAM DOWNSTREAM. SCOUR AT PIER NOSE, NO UNDERMING NOTED. LOW

WATER 8/31/2017.

Bridge Inspection Report

NBI Structure Number: 007401660008200

Effingham 166/082

Elomont	Dataile	1000 4	lisclaimer	halaud

No.	Description	Material Notes and Condition Notes:
12	Reinforced Concrete Deck	CLOSED AND BARRICADED. 5" OF GRAVEL ON DECK. WASHED AT EDGES. CURBS ARE CRACKED AND SPALLED. POST IS BROKEN FROM CURB AT SOUTHWEST.
^L 1130	Cracking (RC and Other)	/
107	Steel Open Girder/Beam	8 STRINGERS.
		HEAVILY RUSTED WITH SCALE AND SECTION LOSS AT ABUTMENTS AND EXTERIORS. GIRDERS #1, 2, 3 AND 7 ARE HOLED THROUGH WEB AND FLANGE AT WEST; GIRDERS #4, 5, 6 AND 8 HAVE HEAVY RUSTING WITH SCALE AND SECTION LOSS. GIRDERS #2, 6, AND 7 ARE HOLED THROUGH WEB AND FLANGE AT EAST ABUTMENT; GIRDERS #3 AND 4 HAVE LIGHT TO MODERATE RUSTING AND GIRDERS #1 AND 8 HAVE HEAVY SECTION LOSS. HEAVY SECTION LOSS AND SCALE EXTENDS OUT TYPICALLY TO ABOUT THREE FEET FROM ABUTMENT FACE (ROUGHLY FIVE FEET FROM BACKWALL). TIMBER FORMS THAT ARE IN PLACE IN MOST AREAS ARE HIDING MORE SECTION LOSS.
^L 515	Steel Protective Coating	
^L 1000	Corrosion	
210	Reinforced Concrete Pier Wall	LIGHT CRACKS AND MINOR SPALLS. UNDERMINED AT SOUTH (SOME SCOUR PRESENT BUT NO UNDERMINING NOTED 8/24/2015, 8/31/2017, 8/16/2019).
215	Reinforced Concrete Abutment	ABUTMENTS HAVE LIGHT CRACKS, SPALLS AND SMALL DELAMINATIONS. WINGS - STONEWORK WITH VOIDS, SETTLED, UNSTABLE. SOME STONE FALLEN.

Element States (see disclaimer below)

No.	Description	Quantity	Units	State 1	State 2	State 3	State 4
12	Reinforced Concrete Deck	667	sq.ft	0%	100%	0%	0%
^L 1130	Cracking (RC and Other)	667	sq.ft	0%	100%	0%	0%
107	Steel Open Girder/Beam	289	ft	0%	0%	70%	30%
L, 515	Steel Protective Coating			0%	0%	100%	0%
^L 1000	Corrosion	288	ft	0%	0%	70%	30%
210	Reinforced Concrete Pier Wall	20	ft	0%	100%	0%	0%
215	Reinforced Concrete Abutment	39	ft .	. 0%	100%	0%	0%
330	Metal Bridge Railing	249	ft	0%	90%	. 0%	10%

Element Disclaimer: NHDOT is transitioning from CoRe elements to AASHTO elements. The AASHTO element data shown above is the product of the automated element migration routine from the AASHTOWare BrM software. This migrated data has undergone limited field verification. Adequate quality control of this element data is not expected to be achieved until the conclusion of the 2020 inspection season. Please utilize element data with caution.

Bridge Notes:

OVERWEIGHT TRUCKING WITNESSED WHILE AT SITE BY LOADED TRI-AXLE DUMP TRUCK ON 8/24/2015.

Inspection Notes: 08/16/2019

MAS - inspection comments -BRIDGE IS CLOSED AND BARRICADED

MAS - inspection comments - BRIDGE IS CLOSED AND BARRICADED

DECK: GRAVEL - WASHED AT DECK EDGES. CURBS - CRACKED AND SPALLED. RAIL - DAMAGED, POST BROKEN AWAY FROM CURB
AT SOUTHWEST. SOFFIT - LIGHT CRACKS AND LEAKING WITH EFFLORESCENCE; DELAMINATIONS AND SPALLS WITH REBAR
EXPOSED. TIMBER FORMS IN PLACE IN AREAS.
SUPERSTRUCTURE: GIRDERS - HEAVILY RUSTED WITH SCALE AND SECTION LOSS AT ABUTMENTS AND EXTERIORS. SEVERAL
WEBS AND FLANGES ARE HOLED AT ABUTMENTS FOR UP TO 39" IN LENGTH. HEAVY SECTION LOSS EXTENDS OUT TYPICALLY TO
ABOUT THREE FEET FROM ABUTMENT FACE (ROUGHLY FIVE FEET FROM BACKWALL).
SUBSTRUCTURE: ABUTMENTS - CRACKS, DELAMINATIONS AND SEVERAL SPALLS. PIER - CRACKS, DELAMINATIONS AND SPALLS.
SCOUR - AT PIER NOSE, NO UNDERMINING NOTED.

NHDOT 008 Inspection Printed on: 1/17/2020 10:06:48 AM Effingham 166/082 Page 3 of 4

Effingham 166/082

Bridge Inspection Report

NBI Structure Number: 007401660008200

Previous Inspection Notes: 10/26/2018

MAS - inspection comments - BRIDGE IS CLOSED AND BARRICADED
DECK: GRAVEL - WASHED AT DECK EDGES. CURBS - CRACKED AND SPALLED. RAIL - DAMAGED, POST BROKEN AWAY FROM CURB
AT SOUTHWEST. SOFFIT - LIGHT CRACKS AND LEAKING WITH EFFLORESCENCE; DELAMINATIONS AND SPALLS WITH REBAR

EXPOSED. TIMBER FORMS IN PLACE IN AREAS.

SUPERSTRUCTURE: GIRDERS - HEAVILY RUSTED WITH SCALE AND SECTION LOSS AT ABUTMENTS AND EXTERIORS. SEVERAL
WEBS AND FLANGES ARE HOLED AT ABUTMENTS FOR UP TO 39" IN LENGTH. HEAVY SECTION LOSS EXTENDS OUT TYPICALLY TO
ABOUT THREE FEET FROM ABUTMENT FACE (ROUGHLY FIVE FEET FROM BACKWALL).

SUBSTRUCTURE: ABUTMENTS - CRACKS, DELAMINATIONS AND SEVERAL SPALLS. PIER - CRACKS, DELAMINATIONS AND SPALLS.

SCOUR - AT PIER NOSE, NO UNDERMINING NOTED.

Approach and Roadway Notes:

GRAVEL - (7) GOOD CONDITION, WASHED. W- BEAM RAIL - DAMAGED. STONE WINGS UNSTABLE. MODERATE VEGETATION.

Inspection History

Inspection	Inspector	Inspection Type(s) Performed			Major Element Ratings				Red	Posting	
Date	Initials	NBI	Elem	FCM	U/W	Deck	Super	Sub	Culvert	list	Posung
08/16/2019	MAS	✓	V			5	2	5	N	\	Bridge Closed
10/26/2018	MAS	V	~			5	2	5	N	V	Bridge Closed
08/31/2017	MAS	V	V			5	2	5	N	V	Bridge Closed
12/01/2016	MAS	V	>			- 5	2	- 5	N	V	Bridge Closed
08/24/2015	MAS	V	>			5	2	5	N	V	Bridge Closed
12/08/2014	MAS	V	V			5	3	5	N	V	6 Tons
08/23/2013	TDC	✓	>			5	3	5	· N	V	6 Tons
10/12/2012	KJT	V	~			5	3	5	N	✓	6 Tons
12/08/2011	KJT	✓	V			5	3	5	N	V	6 Tons
10/26/2010	DPC	✓	V			5	3	5	N	✓	6 Tons
12/11/2009	DPC	✓	V			5	3	5	N	V	6 Tons
08/27/2008	KJT	V	✓.			5	3	6	N	V	6 Tons
12/13/2007	KJT	✓	✓			5	3	7	N	V	6 Tons
09/19/2006	DPC	V	✓			5	3	7	N	✓	6 Tons
12/15/2005	DPC	V	V			5	3	6	N	V	6 Tons
08/25/2004	DPC	V	✓		. 🗀	5	3	7	N	V	6 Tons
02/04/2004	DPC	V	V			5 .	3	7	N	V	6 Tons
04/17/2003	RLM	V	V			5	3	7	N	V	6 Tons
10/03/2002	DPC	V	V			5	5	7	N	V	6 Tons
11/29/2001	DPC	V	V			5	5	7	N	V	6 Tons
10/19/2000	DPC	V	V			5	5	7	N	V	6 Tons
12/09/1999	RLM	V	~			6	5	7	N	✓	6 Tons
10/02/1998	DPC	V	~			6	5	7	N	V	6 Tons
10/01/1997		V	~			6	5	7	N	V	6 Tons
02/01/1996		V	V			6	5	7	N	V	6 Tons
02/01/1994		V	V			6	5	7	N	V	6 Tons
09/01/1992		V	V			7	5	7	N	V	6 Tons

Inspection Frequency (mo.)									
NBI Elem FCM U/W									
16	16	N/A	N/A						

DATE: 27/25/15 NBG DATE: 8/25/2015 EFFINGHAM DEP OVER: SOUTH RIVER BRIDGE NUMBER: CHECK BY: RATED BY: TOWN: PLAN FILE: UNKNOWN DESIGN METHOD: FIELD EVAL. & ENG. JUDGMENT GRANITE ROAD UNKNOWN BRIDGE CAPACITY SUMMARY RATING METHOD: DESIGN LOAD: Form 4 N.H. D.O.T. ROUTE:

·						-						
DED	POSTING			· .			 				, and	
SINGLE LANES LOADED	OPERATING	HS 0.0					 	,			Motric Tops	0.0
AVAILABLE CAFACITI (IIIS 1918) ADED SIN	INVENTORY	HS 0.0						-			E de	English 10ns
AVAILABLE CAI ADED	POSTING								·			Engu 64. (Op.)
AVAL MULTIPLE LANES LOADED	OPERATING	HS 0.0								 		Method By Insp
MULT	INVENTORY	HS 0.0								*		Rating Method (Op.) 63. By Insp
(S Tons) VEHICLES	MULTIPLE UNIT	HS 24.7								 		ANTERNATION OF THE STATE OF THE
REQUIRED CAPACITY (HS Tons) ENT CERTIFIED VEHICLES	SINGLE	HS 27.5					/					
CITRRENT	LEGAL	HS 22.5										"BRIDGE CLOSED" and barricaded
LONGITUD.	SPAN	0-,91			1							"BRIDGE CLOS
RATED	MEMBER	STEEL BEAMS, Shear (100% losses in beam webs)										RECOMMENDED POSTING:
		J	··		<u> </u>							

Power State Control of State Control of

0.0

0.0

66. (Inv.)

By Insp