

# THE STATE OF NEW HAMPSHIRE DEPARTMENT OF TRANSPORTATION

February 27, 2019



Victoria F. Sheehan Commissioner

Claudia Lamphier Effingham Town Administrator 68 School Street Effingham, NH 03844

RE:

COPY OF INTERIM INSPECTION REPORTS OF MUNICIPALLY OWNED BRIDGES AND NHDOT'S RECOMMENDED BRIDGE POSTINGS FOR WEIGHT, HEIGHT, WIDTH, AND/OR CLOSURE

TOWN OF EFFINGHAM

Dear Ms. Lamphier:

Enclosed are copies interim bridge inspection reports for three municipally owned bridges in the Town of Effingham which have been made to update our annual submission to the Federal Government.

In addition, NHDOT'S recommended bridge postings for weight, height, width, and/or closure are noted below. Please note that **Red List bridges** are in **bold type**.

Bridge #	<u>Location</u>	NHDOT Recommended Posting
165/112	Snow Road over South River	E2 Weight Posting
166/082	Granite Road over South River	Bridge Closed Closure Posting Barricades Required
181/072	Stevens Road over Brook	No Posting Recommended

Please note if there are any changes in the recommended weight postings, width postings, height postings, closure postings, or lack of postings for your bridge. Even though a bridge may be recommended for a weight, height, width or closure posting by the State, the decision to properly post or close the structure is the responsibility of the municipal officials. It is in the best interest of the municipality to post or sign your bridges in accordance with these recommendations. A failure to warn motorists of potential bridge hazards could result in tort liability claims. Also, if your bridges are not posted properly, it will result in forfeiture of any possible Federal highway funds for projects in your municipality.

Our bridge inspectors have indicated that the bridges listed above are in compliance with DOT's closure posting recommendation; therefore <u>no posting or closure action needs to be taken by the Town</u>. Please call if there are any questions.

Sincerely.

C. R. Willeke, P.E.

Municipal Highways Engineer

R Wllehe

Bureau of Planning and Community Assistance Tel.: (603) 271-6472 / Fax: (603) 271-8093

CRW Enclosures

cc: Commissioner, Department of Education

S:\Planning\Community Assistance\1-Municipalities\Effingham\Bridge Insp\Interim 2-27-19.doc

# **Bridge Inspection Report**

NBI Structure Number: 007401650011200

Date of Inspection: 10/31/2018

Date Report Sent: 01/09/2019

**Existing Bridge Section** Bureau of Bridge Design

Effingham 165/112

SNOW ROAD

**SOUTH RIVER** 

Owner: Municipality

Bridge Inspection Group: C-Team Bridge Maintenance Crew: OTHER

**Recommended Postings:** 

Weight: E-2

SIGNS IN PLACE 10/31/2018.

✓ Weight Sign OK

Width: Not Required

✓ Width Sign OK

Primary Height Sign Recommendation: None

Optional Centerline Height Sign Rec: None

Clearances:

99.99 Over:

✓ Height Sign OK

(Feet) Under: 0.00

Route: 99.99

Condition:

Red List Status: Municipal Redlist

Deck: N N/A (NBI)

Superstructure: N N/A (NBI)

Substructure: N N/A (NBI)

Culvert: 3 Serious

Sufficiency Rating: 44%

**NBI Status: Structurally Deficient** 

6.0 ft

0.0 ft

0.0 ft

20.0 ft

Bridge Rail: Substandard

Rail Transition: Substandard

Bridge Approach Rail: Substandard

Approach Rail Ends: Substandard

Structure Type and Materials:

Number of Main Spans:

Number of Approach Spans:

Main Span Material and Design Type

Steel Culvert

NH Bridge Type: MP (Metal Pipe)

Deck Type: No Deck ( N/A - NBI)

Wearing Surface: No Deck (N/A - NBI)

Membrane: No Deck (N/A - NBI)

Deck Protection: No Deck (N/A - NBI)

Curb Reveal: 0 in

Plan Location: unknown

Total Bridge Length:

32.0 ft

Right Curb/Sidewalk Width:

0.0 ft

0.0 ft

Total Bridge Width:

Median: No median

Bridge Skew: 0.00°

Year Built/Rebuilt: 1972

Detour Length:

2:0 mi

NHDOT 008 Inspection

**Bridge Dimensions:** 

Length Maximum Span:

Width Curb to Curb:

(W/Shoulders)

Left Curb/Sidewalk Width:

Approach Roadway Width:

Effingham 165/112

Printed on: 1/9/2019 9:54:25 AM Page 1 of 4

FFB 11 REC'D

# **Bridge Inspection Report**

NBI Structure Number: 007401650011200

Existing Bridge Section Bureau of Bridge Design

Effingham 165/112

**Bridge Service:** 

Type of Service on Bridge: Highway

Type of Service Under: Waterway

Lanes on Bridge: 2

Lanes Under: Not Applicable

AADT: 80

Percent Trucks: 0%

Year of AADT: 2015

Future AADT: 118

Year of Future AADT: 2039

Federal or State Definition Bridge: Fed-Definition Bridge

National Highway System: Bridge does not carry NHS

Roadway Functional Class: Rural Local

New Hampshire Highway System and Class: Municipal Highway Eligibility for the National Register of Historic Places: Possibly eligible

Traffic Direction: Two-way traffic

# Effingham 165/112

# **Bridge Inspection Report**

NBI Structure Number: 007401650011200

No.	Description	Material Notes and Condition Notes:
240	Steel Culvert	4 @ 6'-2" CLEAR SPAN ROUND PIPE. 2-2/3" X 1/2" X 8/64" CORRUGATIONS. GALVANIZED STEEL WITH BITUMINOUS COATING.
		HEAVILY RUSTED AND PITTED WITH SCALE. SCATTERED PERFORATIONS AND HOLES. 60% SECTION LOSS IS TYPICAL OF ALL 4 MPS. FEW SMALL TEARS AT INLET ENDS. FEW DENTS AND LIGHT DISTORTION. HEADWALL STONE DROPPED AT SOUTH. STONES MISSING AND LOOSE / UNSTABLE AT NORTH. EROSION BEHIND WING AT NORTHEAST. BEAVER DAM DEBRIS IN ALL PIPES AT INLET ENDS.
<sup>L</sup> 1000	Corrosion	
330	Metal Bridge Railing	
		PLOW DAMAGE. MINOR RUSTING. BROKEN WELDS. NORTHWEST TIPPED DOWN.

#### Element States (see disclaimer below)

No.	Description	Quantity	Units	State 1	State 2	State 3	State 4
240	Steel Culvert	98	ft	0%	0%	40%	60%
<sup>⊥</sup> 1000	Corrosion	98	each	0%	0%	40%	60%
330	Metal Bridge Railing	64	ft	80%	10%	10%	0%

Element Disclaimer: NHDOT is transitioning from CoRe elements to AASHTO elements. The AASHTO element data shown above is the product of the automated element migration routine from the AASHTOWare BrM software. This migrated data has undergone limited field verification. Adequate quality control of this element data is not expected to be achieved until the conclusion of the 2020 inspection season. Please utilize element data with caution.

#### **Bridge Notes:**

ADDED TO THE MUNICIPAL RED LIST 8/24/2015.

HIGH WATER 12/1/16, 10/31/2018.

# Inspection Notes: 10/31/2018

MAS - inspection comments -

CULVERT: ASPHALT - HEAVILY CRACKED AND PATCHED, CRACKS ARE SEALED. METAL PIPE - HEAVY RUSTING AND PITTING WITH SCATTERED PERFORATIONS AND HOLES; 60 % SECTION LOSS IS TYPICAL OF ALL MP'S. THIN WITH FEW SMALL TORN AREAS. FEW DENTS AND LIGHT DISTORTION. HEADWALL STONES ARE MISSING WITH VOIDS AND APPEAR UNSTABLE; EROSION BEHIND WING AT NORTHEAST. BEAVER DAM DEBRIS IN ALL BARRELS. RAIL - PLOW DAMAGE, MINOR RUSTING.

PICTURES: C590-

- 27. STONES MISSING BETWEEN PIPES #3 AND #4 AT NORTH.
- 28. TYPICAL SCATTERED PERFORATIONS.
- 29. BEAVER DAM IN PIPE #2. TYPICAL OF ALL.

#### Previous Inspection Notes: 08/31/2017

MAS - inspection comments -

CULVERT: ASPHALT - HEAVILY CRACKED, DEPRESSED AND PATCHED. METAL PIPE - HEAVY RUSTING AND PITTING WITH SCATTERED PERFORATIONS AND HOLES; 60 % SECTION LOSS IS TYPICAL OF ALL MP'S. THIN WITH FEW SMALL TORN AREAS. FEW DENTS AND LIGHT DISTORTION. HEADWALL STONES ARE MISSING WITH VOIDS AND APPEAR UNSTABLE; EROSION BEHIND WING AT NORTHEAST. BEAVER DAM DEBRIS IN ALL BARRELS. RAIL - PLOW DAMAGE, MINOR RUSTING. LOW WATER 8/31/2017.

#### PICTURES: C574-

- 39. MP #1 IS THIN AND HOLED WITH 60% SECTION LOSS.
- 40. MP #1 IS THIN AND HOLED WITH 60% SECTION LOSS.
- 41. MP #2 IS THIN AND HOLED WITH 60% SECTION LOSS.
- 42. MP #3 IS THIN AND HOLED WITH 60% SECTION LOSS.
- 43. MP #4 IS THIN AND HOLED WITH 60% SECTION LOSS.
- 44. MP #4 IS THIN AND HOLED WITH 60% SECTION LOSS.
  45. STONE DISPLACED BETWEEN #3 AND #4 MP'S AT NORTH.
- 46. SOUTH ELEVATION, BEAVER DAM DEBRIS IN ALL MP'S.

# Approach and Roadway Notes:

ASPHALT- (6) CRACKS ARE SEALED, SETTLED AND PATCHED. W- BEAM RAIL - HEAVILY DAMAGED AND CRACKED WELDS.

EMBANKMENT WASHED WITH EROSION BEHIND WING AT NORTHEAST.

NHDOT 008 Inspection

Printed on: 1/9/2019 9:54:26 AM

# **Bridge Inspection Report**

NBI Structure Number: 007401650011200

Effingham 165/112

### **Inspection History**

Inspection	Inspector	Inspe	ection Typ	e(s) Perfo	ormed	Ma	jor Elen	nent Ra	tings	Red	Docting
Date	Initials	NBI	Elem	FCM	U/W	Deck	Super	Sub	Culvert	list	Posting
10/31/2018	MAS	V	V			N	N	N	3	V	E-2
08/31/2017	MAS	V	V			N	N	N	3	<b>✓</b>	E-2
12/01/2016	KJT	✓	V			N	N	N	4	V	E-2
08/24/2015	MAS	V	V			N	N	N	4	V	E-2
08/16/2013	MAS	V	V			N	N	N	5		E-2
10/12/2012	KJT	V	V			N	N	N	5		E-2
10/22/2010	KJT	V	✓			N	N	N	5		E-2
08/27/2008	KJT	>	<b>V</b>			N	N	N	5		E-2
09/27/2006	RLM	V	✓			N	N	N	5		E-2
08/25/2004	DPC	V	V			N	N	N	5		E-2
10/03/2002	DPC	V	V			N	N	N	5		E-2
10/19/2000	DPC	V	~			N	N	N	5		E-2
10/02/1998	·DPC	V	V			N	N	N	6		E-2
08/01/1996		. ✓	V			N	N	N	6		E-2
09/01/1994		V	<b>✓</b>			N	N	N	6		E-2
09/01/1992		✓	V			N	N	N	N		E-2

Inspe	ction Fre	equency	(mo.)		
NBI	Elem	FCM	U/W		
16	16	N/A	N/A		

N.H. D.O.T. Form 4

12/8/2017 DATE: 12 165/112 EFFINGHAM DATE: NBG OVER: SOUTH RIVER BRIDGE NUMBER: CHECK BY: RATED BY: TOWN: UNKNOWN UNKNOWN DESIGN METHOD: PLAN FILE: LOAD FACTOR SNOW ROAD UNKNOWN BRIDGE CAPACITY SUMMARY RATING METHOD: DESIGN LOAD: ROUTE:

	LONGITUD.	REQUIF	REQUIRED CAPACITY (HS Tons)	4S Tons)			AVAILABLE CA	AVAILABLE CAPACITY (HS Tons)		
RATED	EFFECTIVE	CURRENT	CERTIFIED	CERTIFIED VEHICLES	MUL	MULTIPLE LANES LOADED	ADED	NIS	SINGLE LANES LOADED	DED
MEMBER	SPAN	LEGAL LOADS	SINGLE	MULTIPLE	INVENTORY	OPERATING	POSTING	INVENTORY	OPERATING	POSTING
Corrugated Metal Pipes (1'-6" of fill, 60% losses)	3:-0"	HS 14.0	HS 15.4	HS 15.4	HS 13.1	HS 21.8		HS 13.1	HS 21.8	·
					•					
		•								
								, .		
-										
-										
								,		
		-								
RECOMMENDED POSTING:	E-2				Rating (Op.) 63.	Rating Method 63. LF	Engli 64. (Op.)	English Tons 39.2	Metric Tons 35.6	SI
			***************************************			<b>!</b>				
			WEW HILL	Ü	(Inv.) 65.	LF	66. (Inv.)	23.5	21.3	

(Inv.) 65.  SNOW ROAD over SOUTH RIVER

Wednesday, October 31, 2018


STONES MISSING BETWEEN PIPES #3 AND #4 AT NORTH. (RL)



C590 27

Wednesday, October 31, 2018

TYPICAL SCATTERED PERFORATIONS. (RL)



C590 28

Wednesday, October 31, 2018

BEAVER DAM IN PIPE #2. TYPICAL OF ALL. (RL)



C590 29

# **Bridge Inspection Report**

NBI Structure Number: 007401660008200

Date of Inspection: 10/26/2018

Date Report Sent: 01/09/2019

Existing Bridge Section Bureau of Bridge Design

Effingham 166/082

**GRANITE ROAD** 

**SOUTH RIVER** 

✓ Weight Sign OK

✓ Width Sign OK

Owner: Municipality

Bridge Inspection Group: C-Team Bridge Maintenance Crew: OTHER

**Recommended Postings:** 

Weight: 'Bridge Closed' and barricaded at both ends

36%

CLOSED AND BARRICADED 10/26/2018.

Width: Narrow Bridge

Sufficiency Rating:

Bullet holes in signs, still legible.

✓ Height Sign OK Primary Height Sign Recommendation: None Clearances: Over: 99.99

0.00 (Feet) Under: Optional Centerline Height Sign Rec: None

Route: 99.99

Structure Type and Materials: Condition:

**Number of Main Spans:** 2 Red List Status: Municipal Redlist

Number of Approach Spans: Deck: 5 Fair Superstructure: 2 Critical

Main Span Material and Design Type Substructure: 5 Fair Steel Continuous Multiple Beam

Culvert: N N/A (NBI)

**NBI Status: Structurally Deficient** 

Bridge Rail: Substandard NH Bridge Type: IB-C (I Beams w/ Concrete Deck)

Rail Transition: Substandard Deck Type: Concrete, Cast in Place

Wearing Surface: Other Bridge Approach Rail: Substandard Approach Rail Ends: Substandard Membrane: None Deck Protection: None

Curb Reveal: Not Measured

Plan Location: N-O-F **Bridge Dimensions:** 

Total Bridge Length: 36.0 ft Length Maximum Span: 14.0 ft Right Curb/Sidewalk Width: 0.0 ft Left Curb/Sidewalk Width: 0.0 ft

Total Bridge Width: 18.5ft Width Curb to Curb: 17.8 ft

Median: No median 14.0 ft Approach Roadway Width:

(W/Shoulders) Bridge Skew: 0.00° Year Built/Rebuilt: 1920/1950 Detour Length: 2.0 mi

Printed on: 1/9/2019 9:54:33 AM NHDOT 008 Inspection Effingham 166/082 Page 1 of 4

# **Bridge Inspection Report**

NBI Structure Number: 007401660008200

**Existing Bridge Section** Bureau of Bridge Design

Effingham 166/082

**Bridge Service:** 

Type of Service on Bridge: Highway Type of Service Under: Waterway

Lanes on Bridge: 2

Lanes Under: Not Applicable

AADT:

60

Percent Trucks: 0%

Year of AADT: 1985

88 Future AADT:

Year of Future AADT: 2039

Federal or State Definition Bridge: Fed-Definition Bridge

National Highway System: Bridge does not carry NHS

Roadway Functional Class: Rural Local

New Hampshire Highway System and Class: Municipal Highway Eligibility for the National Register of Historic Places: Possibly eligible

Traffic Direction: Two-way traffic

.. . .

# **Bridge Inspection Report**

NBI Structure Number: 007401660008200

. . . . . .

Effingham 166/082

No.	Description	Material Notes and Condition Notes:
12	Reinforced Concrete Deck	
		CLOSED AND BARRICADED. 5" OF GRAVEL ON DECK. WASHED AT EDGES. CURBS ARE CRACKED AND SPALLED. POST IS BROKEN FROM CURB AT SOUTHWEST.
<sup>L</sup> 1130	Cracking (RC and Other)	
107	Steel Open Girder/Beam	8 STRINGERS.
!		HEAVILY RUSTED WITH SCALE AND SECTION LOSS AT ABUTMENTS AND EXTERIORS. GIRDERS #1, 2, 3 AND 7 ARE HOLED THROUGH WEB AND FLANGE AT WEST; GIRDERS #4, 5, 6 AND 8 HAVE HEAVY RUSTING WITH SCALE AND SECTION LOSS. GIRDERS #2, 6, AND 7 ARE HOLED THROUGH WEB AND FLANGE AT EAST ABUTMENT; GIRDERS #3 AND 4 HAVE LIGHT TO MODERATE RUSTING AND GIRDERS #1 AND 8 HAVE HEAVY SECTION LOSS. HEAVY SECTION LOSS AND SCALE EXTENDS OUT TYPICALLY TO ABOUT THREE FEET FROM ABUTMENT FACE (ROUGHLY FIVE FEET FROM BACKWALL). TIMBER FORMS THAT ARE IN PLACE IN MOST AREAS ARE HIDING MORE SECTION LOSS.
<sup>L</sup> 515	Steel Protective Coating	
· <sup>L</sup> 1000	Corrosion	
210	Reinforced Concrete Pier Wall	
		LIGHT CRACKS AND MINOR SPALLS. UNDERMINED AT SOUTH (SOME SCOUR PRESENT BUT NO UNDERMINING NOTED 8/24/2015, 8/31/2017).
215	Reinforced Concrete Abutment	
		ABUTMENTS HAVE LIGHT CRACKS, SPALLS AND SMALL DELAMINATIONS. WINGS - STONEWORK WITH VOIDS, SETTLED, UNSTABLE. SOME STONE FALLEN.
330	Metal Bridge Railing	
		NO OFFSET BLOCKS. POST BROKEN SOUTHWEST. W - BEAM DAMAGED.

#### Element States (see disclaimer below)

No.	Description	Quantity	Units	State 1	State 2	State 3	State 4
12	Reinforced Concrete Deck	667	sq.ft	0%	100%	0%	0%
<sup>1</sup> 1130	Cracking (RC and Other)	667	sq.ft	0%	100%	0%	0%
107	Steel Open Girder/Beam	289	ft	0%	0%	70%	30%
<sup>L</sup> 515	Steel Protective Coating	_		0%	0%	100%	0%
<sup>L</sup> 1000	Corrosion	288	each	0%	0%	70%	30%
210	Reinforced Concrete Pier Wall	20	ft	0%	100%	0%	0%
215	Reinforced Concrete Abutment	39	ft	0%	100%	0%	0%
330	Metal Bridge Railing	249	ft	0%	90%	0%	10%

Element Disclaimer: NHDOT is transitioning from CoRe elements to AASHTO elements. The AASHTO element data shown above is the product of the automated element migration routine from the AASHTOWare BrM software. This migrated data has undergone limited field verification. Adequate quality control of this element data is not expected to be achieved until the conclusion of the 2020 inspection season. Please utilize element data with caution.

#### **Bridge Notes:**

OVERWEIGHT TRUCKING WITNESSED WHILE AT SITE BY LOADED TRI-AXLE DUMP TRUCK ON 8/24/2015.

#### Inspection Notes: 10/26/2018

MAS - inspection comments -

BRIDGE IS CLOSED AND BARRICADED

DECK: GRAVEL - WASHED AT DECK EDGES. CURBS - CRACKED AND SPALLED. RAIL - DAMAGED, POST BROKEN AWAY FROM CURB AT SOUTHWEST. SOFFIT - LIGHT CRACKS AND LEAKING WITH EFFLORESCENCE; DELAMINATIONS AND SPALLS WITH REBAR EXPOSED. TIMBER FORMS IN PLACE IN AREAS.

SUPERSTRUCTURE: GIRDERS - HEAVILY RUSTED WITH SCALE AND SECTION LOSS AT ABUTMENTS AND EXTERIORS. SEVERAL WEBS AND FLANGES ARE HOLED AT ABUTMENTS FOR UP TO 39" IN LENGTH. HEAVY SECTION LOSS EXTENDS OUT TYPICALLY TO ABOUT THREE FEET FROM ABUTMENT FACE (ROUGHLY FIVE FEET FROM BACKWALL).

SUBSTRUCTURE: ABUTMENTS - CRACKS, DELAMINATIONS AND SEVERAL SPALLS. PIER - CRACKS, DELAMINATIONS AND SPALLS. SCOUR - AT PIER NOSE, NO UNDERMINING NOTED.

NHDOT 008 Inspection

Printed on: 1/9/2019 9:54:33 AM

# Effingham 166/082

# **Bridge Inspection Report**

NBI Structure Number: 007401660008200

Previous Inspection Notes: 08/31/2017

00/31/2017

MAS - inspection comments - BRIDGE IS CLOSED AND BARRICADED

DECK: GRAVEL - WASHED AT DECK EDGES. CURBS - CRACKED AND SPALLED. RAIL - DAMAGED, POST BROKEN AWAY FROM CURB
AT SOUTHWEST. SOFFIT - LIGHT CRACKS AND LEAKING WITH EFFLORESCENCE; DELAMINATIONS AND SPALLS WITH REBAR

EXPOSED, TIMBER FORMS IN PLACE IN AREAS.

SUPERSTRUCTURE: GIRDERS - HEAVILY RUSTED WITH SCALE AND SECTION LOSS AT ABUTMENTS AND EXTERIORS. SEVERAL WEBS AND FLANGES ARE HOLED AT ABUTMENTS FOR UP TO 39" IN LENGTH. HEAVY SECTION LOSS EXTENDS OUT TYPICALLY TO ABOUT THREE FEET FROM ABUTMENT FACE (ROUGHLY FIVE FEET FROM BACKWALL).

SUBSTRUCTURE: ABUTMENTS - CRACKS, DELAMINATIONS AND SEVERAL SPALLS. PIER - CRACKS, DELAMINATIONS AND SPALLS.

SCOUR - AT PIER NOSE, NO UNDERMINING NOTED.

#### Approach and Roadway Notes:

GRAVEL - (7) GOOD CONDITION, WASHED. W- BEAM RAIL - DAMAGED. STONE WINGS UNSTABLE. MODERATE VEGETATION.

#### Inspection History

Inspection	Inspector	Inspe	ction Typ	e(s) Perfo	ormed	Ma	jor Elen	nent Ra	tings	Red	Posting
Date	Initials	NBI	Elem	FCM	U/W	Deck	Super	Sub	Culvert	list	Posung
10/26/2018	MAS	V	V			5	2	5	N	V	Bridge Closed
08/31/2017	MAS	<b>V</b>	V			5	2	5	N	✓	Bridge Closed
12/01/2016	MAS	<b>✓</b>	V			5	2	5	N	V	Bridge Closed
08/24/2015	MAS	✓	$\overline{\mathbf{V}}$			5	2	5	N	V	Bridge Closed
12/08/2014	MAS	✓	V			5	3	5	N	V	6 Tons
08/23/2013	TDC	V	V			5	3	5	N	✓	6 Tons
10/12/2012	KJT	✓	<b>✓</b> .			5	3	. 5	N	>	6 Tons
12/08/2011	KIT	✓	✓			5	3	5	N	✓	6 Tons
10/26/2010	DPC	✓	V			5	3	5	N	✓	6 Tons
12/11/2009	DPC	V	V			5	3	5	N	V	6 Tons
08/27/2008	KJT	V	V			5	3	6	N	V	6 Tons
12/13/2007	KJT	$\mathbf{V}$	V			5	3	7	N	<b>V</b>	6 Tons
09/19/2006	DPC	V	<b>V</b>			5	3	7	N	<b>&gt;</b>	6 Tons
12/15/2005	DPC	V	<b>&gt;</b>			5_	3	6	N	>	6 Tons
08/25/2004	DPC	V	V			5	3	7	N	>	6 Tons
02/04/2004	DPC	V	<b>✓</b>			5	3	7	Ν	$\checkmark$	6 Tons
04/17/2003	RLM	K	<b>V</b>			5	3	7	N	$\checkmark$	6 Tons
10/03/2002	DPC	<b>\</b>	✓			5	5	7	N	V	6 Tons
11/29/2001	DPC	V	<b>V</b>			5	5	7	N	$\checkmark$	6 Tons
10/19/2000	DPC	✓	✓			5	5	7	N	✓	6 Tons
12/09/1999	RLM	<b>~</b>	✓			6	5	7	N	✓	6 Tons
10/02/1998	DPC	✓	V			6	5	7	N	V	6 Tons
10/01/1997		V	V			6	5	7	N	<b>✓</b>	6 Tons
02/01/1996		$\overline{\mathbf{V}}$	V			6	5	7	N	<b>V</b>	6 Tons
02/01/1994		V	V			6	5	7	N	V	6 Tons
09/01/1992		V	V			7_	5	7	N	<b>V</b>	6 Tons

Insped	ction Fre	equency	(mo.)
NBI	Elem	FCM	U/W
16	16	N/A	N/A

166/082 DATE: EFFINGHAM \_ DATE: DEF NBG OVER: SOUTH RIVER BRIDGE NUMBER: CHECK BY: RATED BY: TOWN: UNKNOWN UNKNOWN DESIGN METHOD: PLAN FILE: FIELD EVAL. & ENG. JUDGMENT GRANITE ROAD UNKNOWN BRIDGE CAPACITY SUMMARY RATING METHOD: DESIGN LOAD: Form 4 N.H. D.O.T. ROUTE:

8/25/2015

		NG NG		
	<u>B</u>	POSTING		suc
	SINGLE LANES LOADED	OPERATING	HS 0.0	Metric Tons 0.0
AVAILABLE CAPACITY (HS Tons)	SINC	INVENTORY	HS 0.0	English Tons
AVAILABLE CAP	DED	POSTING		Engl
,	MULTIPLE LANES LOADED	OPERATING	HS 0.0	Rating Method
	MULT	INVENTORY	HS 0.0	Rating
S Tons)	VEHICLES	MULTIPLE UNIT	HS 24.7	
REQUIRED CAPACITY (HS Tons)	CERTIFIED VEHICLES	SINGLE	HS 27.5	
REQUIR	CURRENT	LEGAL	HS 22.5	Lot comment to a floring to a contract
LONGITUD.	EFFECTIVE	SPAN	16'-0"	
	RATED	MEMBER	STEEL BEAMS, Shear (100% losses in beam webs)	

David Charles Charles

0.0

0.0

66. (Inv.)

By Insp

# Bridge Inspection Report

NBI Structure Number: 007401810007200

Existing Bridge Section Bureau of Bridge Design

Effingham 181/072

Date of Inspection: 12/11/2018

Date Report Sent: 01/09/2019

Owner: Municipality

Bridge Inspection Group: C-Team Bridge Maintenance Crew: OTHER **STEVENS ROAD** 

over

**BROOK** 

#### **Recommended Postings:**

Weight: No Posting Required

Weight Sign OK

Width: Not Required

**✓** Width Sign OK

Primary Height Sign Recommendation: None

Optional Centerline Height Sign Rec: None

Clearances:

Over: aa aa ✓ Height Sign OK

(Feet)

Under: 0.00

99.99 Route:

#### Condition:

Red List Status: Not on the Redlist

Deck: N N/A (NBI)

Superstructure: N N/A (NBI)

Substructure: N N/A (NBI)

Culvert: 9 Excellent

Sufficiency Rating: 100%

NBI Status: Not Applicable

Bridge Rail: N/A or Not Required

Rail Transition: N N/A or not required

Bridge Approach Rail: Meets Standards

Approach Rail Ends: Meets Standards

**Bridge Dimensions:** 

Length Maximum Span:

10.0 ft

Left Curb/Sidewalk Width:

0.0 ft

Width Curb to Curb:

0.0 ft

Approach Roadway Width:

18.0ft

(W/Shoulders)

# **Structure Type and Materials:**

Number of Main Spans:

Number of Approach Spans: 0

Main Span Material and Design Type

**Prestressed Concrete Culvert** 

NH Bridge Type: CB-P (Concrete Box-Precast)

Deck Type: No Deck (N/A - NBI)

Wearing Surface: No Deck (N/A - NBI)

Membrane: No Deck (N/A - NBI)

Deck Protection: No Deck (N/A - NBI)

Curb Reveal: Not Measured

Plan Location: N-O-F

Total Bridge Length:

10.0 ft

Right Curb/Sidewalk Width:

0.0ft

0.0 ft

Total Bridge Width:

Median: No median

Bridge Skew: 5.00°

Year Built/Rebuilt: 2018 Detour Length:

2.0 mi

NHDOT 008 Inspection

Printed on: 1/9/2019 9:54:37 AM

Page 1 of 4

Effingham 181/072

# **Bridge Inspection Report**

NBI Structure Number: 007401810007200

Existing Bridge Section Bureau of Bridge Design

Effingham 181/072

**Bridge Service:** 

Type of Service on Bridge: Highway

Type of Service Under: Waterway

Lanes on Bridge: 2

Lanes Under: Not Applicable

AADT:

230

Percent Trucks: 10 %

Year of AADT: 1987

Future AADT:

340

Year of Future AADT: 2039

Federal or State Definition Bridge: NH-Definition Bridge

National Highway System: Bridge does not carry NHS

Roadway Functional Class: Rural Local

New Hampshire Highway System and Class: Municipal Highway

Eligibility for the National Register of Historic Places: Not Eligible

Traffic Direction: Two-way traffic

# **Bridge Inspection Report**

NBI Structure Number: 007401810007200

Effingham 181/072

#### Element Details (see disclaimer below)

No.	Description	Material Notes and Condition Notes:
215	Reinforced Concrete Abutment	Element record added 12/11/2018 4 PRECAST CONCRETE WINGS.
)		PRECAST CONCRETE WINGS. NEW CONDITION. MINOR INSTALLATION DAMAGE,
245	Prestressed Concrete Culvert	Element record added 12/11/2018 4 PRECAST CONCRETE BOX SECTIONS, 10" THICK.
		NEW PRECAST CONCRETE BOX 10" THICK.

#### Element States (see disclaimer below)

No.	Description	Quantity	Units	State 1	State 2	State 3	State 4
215	Reinforced Concrete Abutment	40	ft	100%	0%	0%	0%
245	Prestressed Concrete Culvert	26	ft	100%	0%	0%	0%

Element Disclaimer: NHDOT is transitioning from CoRe elements to AASHTO elements. The AASHTO element data shown above is the product of the automated element migration routine from the AASHTOWare BrM software. This migrated data has undergone limited field verification. Adequate quality control of this element data is not expected to be achieved until the conclusion of the 2020 inspection season. Please utilize element data with caution.

#### **Bridge Notes:**

REMOVED FROM MUNICIPAL RED LIST 12/11/2018. NEW PRECAST CONCRETE CULVERT 12/11/2018.

Inspection Notes: 12/11/2018

MAS - inspection comments -

CULVERT: GRAVEL - GOOD CONDITION, ICE AND SNOW COVERED. CONCRETE BOX - NEW CONDITION. WINGS - NEW CONDITION,

MINOR INSTALLATION SPALLS.

PICTURES: C591-07. WEST APPROACH. 08. SOUTH ELEVATION.

Previous Inspection Notes: 08/31/2017

KJT - inspection comments -

DECK: GRAVEL - GOOD CONDITION. RAIL - MINOR DAMAGE. JERSEY BARRIERS AT SOUTH ONLY. SOFFIT - FORMS IN PLACE. SUPERSTRUCTURE: MASONRY SLABS APPEAR TO BE IN GOOD CONDITION WITH NONE FRACTURED. I BEAMS ARE RUSTED WITH SCALE AT EXPOSED BEAM FLANGES.

SUBSTRUCTURE: STONE MASONRY HAS VOIDS AT BASES, MORTAR MISSING. WINGS ARE SETTLED AND UNDERMINED, EMBANKMENT IS WASHED. SOUTHEAST ABUTMENT AND WING SETTLED AND UNDERMINED WITH UP TO 5' PENETRATION X 3' WIDE. NORTHWEST ABUTMENT AND WING SETTLED AND UNDERMINED WITH UP TO 5' PENETRATION X 1' WIDE.

PICTURE:C574.

47. JERSEY BARRIERS AT SOUTH.

#### Approach and Roadway Notes:

GRAVEL - (7) GOOD CONDITION. W- BEAM RAIL - NEW CONDITION.

Unusual or experimental features:

# Effingham 181/072

# **Bridge Inspection Report**

NBI Structure Number: 007401810007200

Inspection History

Inspection	Inspector	Inspe	ction Typ	e(s) Perfo	ormed	Ma	ajor Elen	nent Ra	tings	Red	Posting
Date	Initials	NBI	Elem	FCM	U/W	Deck	Super	Sub	Culvert	list	rosting
12/11/2018	MAS	<b>V</b>	<b>V</b>			N	N	N	9		No Posting Req'd
08/31/2017	KJT	<b>V</b>	✓			5	5	3	N	<b>V</b>	6 Tons
12/01/2016	KJT	V	<b>V</b>			5	5	3	N	<b>V</b>	6 Tons
08/24/2015	KJT	<b>V</b>	<b>V</b>			5	5	3	N	<b>V</b>	6 Tons
12/08/2014	MAS	<b>V</b>	<b>V</b>			5	5	3	N	V	6 Tons
08/23/2013	MAS	<b>V</b>	<b>✓</b>			5	5	3	N	<b>V</b>	6 Tons
10/12/2012	MAS	V	<b>V</b>			5	5	3	N.	V	6 Tons
12/08/2011	MAS	V	V			5	5	3	N	V	6 Tons
10/26/2010	DPC	<b>V</b>	V			5	5	3	N	V	6 Tons
12/11/2009	KJT	V	<b>V</b>			5	5	3	N	V	6 Tons
08/26/2008	DPC	V	V			5	5	3	N	<b>V</b>	6 Tons
12/13/2007	KJT	~	<b>V</b>			5	5	. 5	N	V	6 Tons
09/19/2006	RLM	V	~			5	5	5	N	<b>V</b>	6 Tons
12/15/2005	RLM	~	<b>V</b>			5	5	5	N	<b>V</b>	6 Tons
08/25/2004	DPC	~	<b>V</b>			5	5	5	N	<b>V</b>	6 Tons
02/04/2004	RLM	<b>V</b>	V			5	5	5	N	>	6 Tons
04/17/2003	DPC	<b>\</b>	<b>V</b>			5	5	5	N	>	6 Tons
10/03/2002	DPC	<b>V</b>	<b>V</b>			5	5	5	N	>	6 Tons
11/29/2001	DPC	<b>✓</b>	>			5	5	5	N	<b>✓</b>	6 Tons
10/19/2000	RLM	<b>V</b>	>			6	6	5	N	<b>V</b>	6 Tons
12/09/1999	DPC	<b>V</b>	>			6	6	5	. N	>	6 Tons
10/02/1998	FNM	<b>V</b>	<b>✓</b>			6	6	6	. N	<b>\</b>	6 Tons
10/01/1997		<b>\</b>	<b>V</b>			6	6	6	N	>	6 Tons
02/01/1996		<b>V</b>	<b>V</b>			6	6	6	N	<b>V</b>	6 Tons
02/01/1994		<b>V</b>	<b>V</b>			6	6	6	N	<b>V</b>	6 Tons
09/01/1992		<b>V</b>	<b>V</b>			6	6	6	N	<b>V</b>	6 Tons

Inspe	ction Fre	equency	(mo.)
NBI	Elem	FCM	U/W
24	24	N/A	N/A

Form 4 N.H. D.O.T.

BRIDGE CAPACITY SUMMARY

STEVENS ROAD

ROUTE:

118/2019 DATE: DATE TL RATED BY: LRFD (ASSUMED) SCANNED PLANS DESIGN METHOD: PLAN FILE: FIELD EVAL. & ENG. JUDGMENT HL-93 (ASSUMED) RATING METHOD: DESIGN LOAD:

CHECK BY:

10 Q

1/8/2019

181/072

BRIDGE NUMBER:

TOWN:

EFFINGHAM

OVER: STREAM

	LONGITUD.	REQUIR	REQUIRED CAPACITY (HS Tons)	(S Tons)	11.11	I O I O III O Y II Y III	AVAILABLE CAF	AVAILABLE CAPACITY (HS Tons)	ons)	ED
RATED	EFFECTIVE	CURRENT	CERTIFIED VEHICLES	VEHICLES	MULI	MULTIFLE LANES LOADED	UED	NTY C	מינים מינים מינים	
MEMBER	SPAN	LEGAL	SINGLE	MULTIPLE	INVENTORY	OPERATING	POSTING	INVENTORY	OPERATING	POSTING
Precast Concrete Box Culvert* Flexure Shear	. 10-0"	HS 17.9 HS 22.4	HS 19.7 HS 24.8	HS 17.2 HS 22.3	HS 22.0 HS 27.2	HS 28.5 HS 35.3		HS 22.0 HS 27.2	HS 28.5 HS 35.3	
*Load ratings are assigned per engineeering judgment utilizing inventory rating factors of 1.0 and operating rating factors of 1.296 (=1.75/1.35), corresponding to HL-93 design assumed per the date of construction.								·		
RECOMMENDED POSTING:	- Q	NO POSTING REQUIRED	RED		Rating (Op.) 63.	Rating Method 63. By Insp.	Engl. (Op.)	English Tons 51.3	Metric Tons 46.5	suc
			TO PHILIPPINE THE PARTY OF THE		(Inv.) 65.	By Insp.	66. (Inv.)	39.6	35.9	ı

(Inv.) 65.  Tuesday, December 11, 2018
WEST APPROACH.



C591 07

Tuesday, December 11, 2018
SOUTH ELEVATION.



C591 08

# EFFINGHAM MUNICIPAL BRIDGES

BRIDGE NUMBER	TYPE	TYPE SPANS	ROAD INV.NO.	ROAD NAME	OVER	(0-T-0)	POSTING
080/113	IB-C	<b></b>	82	ELM STREET	PINE RIVER	62'-0"	E-2
097/088	JACK	<del></del>	<b>83</b>	DRAKE ROAD	WILKINSON BROOK 22'-0"	22'-0"	WEIGHT LIMIT 6 TONS; ONE LANE BRIDGE
165/112	MP	4	68	SNOW ROAD	SOUTH RIVER	32'-0"	E-2
166/082	<b>В-С</b>	2	65	GRANITE ROAD	SOUTH RIVER	36'-0"	BRIDGE CLOSED
176/185	HT	1	53	HUNTRESS BRIDGE ROAD	OSSIPEE RIVER	139'-0"	NO POSTING REQ'D; MIN. VERT. CLR. 12'-03"
181/072	Св-Р	<b>,</b>	63	STEVENS ROAD	BROOK	10'-0"	NO POSTING REQ'D;

REMARKS: 166/082 SENT AS A CRITICAL DEFICIENCY ON 8/25/2015.

166/100 REMOVED FROM THE INVENTORY (PRIVATE BRIDGE PER TOWN DOCUMENTS).

REVISED/REVIEWED: 1/19