



FIELD REPORT #002

HEB Engineers, Inc. • www.hebengineers.com

New Hampshire: Office (603) 356-6936 • Fax (603) 356-7715 • PO Box 440 • 2605 White Mountain Hwy • North Conway, NH 03860

Maine: Office (207) 803-8265 • PO Box 343 • 103 Main Street • Suite 6 • Bridgton, ME 04009

Date:	May 25, 2021	Project #:	2018-087	<i>Page 1 of 2</i>
To:	Town of Effingham 68 School Street Effingham, NH 03882	Project:	Snow Road Bridge Replacement	
		Location:	Effingham, NH	
Email:	townofeffingham@effinghamnh.net	Owner:	Town of Effingham	
Prepared By:	Eric V. Schroeder, EIT	Contractor:	Hansen Bridge LLC	
Reviewed & Approved By:	Christopher R. Fournier, PE	Weather Conditions:	61°F Sunny	

SITE VISIT

Arrived at site: 9:01 AM **Left site at:** 1:46 PM

Personnel & Equipment on site:

- HEB Engineers, Inc. (HEB): Eric V. Schroeder, EIT
- Hansen Bridge LLC (Contractor): Mike Hansen (Superintendent), 1 Laborer
- Hansen Bridge LLC Equipment:
 - 1 Volvo Excavator, VE1336 (idle)
 - 1 Low Bed, USDOT752325 (idle)

Visitors to Site:

- Town of Effingham: Mike Cahalane, Chuck Fuller

Purpose of Site Visit:

- To observe construction progress.

Work Performed by Contractor since last site visit:

- Four (4) jersey barriers were added to the bridge closure.
- Survey benchmarks were found and identified.

Items Discussed and Observed:

- Contractor said that GM2 Associates Inc. (GM2), Hansen's subconsultant, will be on-site to layout centerline bearing on either side of bridge prior to construction. They will also be marking each pile location.
- Contractor said they will post NHDES (New Hampshire Department of Environmental Services) Wetlands Permit on site prior to starting construction.
- Contractor said they will install erosion controls according to the NHDES Wetlands Permit prior to construction.

Work Scheduled:

- Wednesday, May 26, 2021 – GM2 to mark centerline bearing. Contractor to begin driving H-Piles.

Outstanding Construction Issues:

- None.

Next Observation:

- Wednesday, May 26, 2021.

Please notify HEB if any information is missing from this field report or has been interpreted differently.

Photos:

- Taken by EVS on May 25, 2021.



Photo 1: MagNail #1 found and identified.



Photo 2: H-Piles delivered to site.

Copy: Hansen Bridge LLC
File

P:\Jobs\2018\2018-087 Effingham - Snow Road Bridge #165-112 over South River, Effingham, NH\Construction Observation\Field Reports\Snow Road Bridge - Field Report #002 05-25-21.doc

Please notify HEB if any information is missing from this field report or has been interpreted differently.